Strategic Flood Risk Assessment



ID	Location	Flooded	Notes
1	N.Elham	1994 & 2000/01	Fluvial Flooding - Main River Nailbourne exceeded culvert capacity - Flooded properties
2	Water Farm Elham	2000/01	Sewer Flooding - Public foul sewer surcharged and flooded 1 property seriously
3	Elham (Water Cottage Duck St)	2000/01	Fluvial Flooding -Nailbourne Main River overtopped banks due to blocked grill - 14 properties affected (internal flooding) Hog Green
4	Ottinge	2000/01	Fluvial Flooding - Nailbourne & surrounding tributaries flooded as a result of a blocked culvert (too small)
5	Lyminge Cricket Grd	2000/01	Groundwater Flooding - Groundwater springs filling up cricket ground approx 600mm deep
6	Lyminge	2000/01	Fluvial Flooding - Nailbourne River overtopped banks - flooded gardens
7	Monks Horton - Kite Manor - Off Stone St	1997 & 2000/01	Surface Water Flooding - Known flooding on 2 occasions
8	Stanford	2000/01 & August 2007	Surface Water Flooding - Road flooded from pub, houses on the bank not affected
9	Stanford	2000/01 & August 2007	Fluvial Flooding - One house flooded (2000/01 & again during recent flash flood Aug 07)
10	Etchinhill (St Marys Drive)	2004-2007 August 2007	Surface Water Flooding - Small number of properties flooded - Internal flooding on several occasions (7 occasions in total)
11	Frogholt	1996& 2001	Surface Water Flooding - Gardens Only (No Properties) - Highway flooded due to restricted grill
12	Newington	1995	Surface Water Flooding - Some properties affected - Deep highway flooding - Occasional big events
13	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
14	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
15	Dolphins Rd Folkestone	Frequent	Highway Flooding - regular occurrence (affecting some properties)
16	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
17	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd

Strategic Flood Risk Assessment



ID	Location	Flooded	Notes
18	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
19	Folkestone Harbour	11-Jun-97	Sewer Flooding - Surface water sewers overwhelmed during flash flooding - approximately 10 properties affected by internal flooding
20	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
21	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
22	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
23	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
24	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
25	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
26	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1 - Some areas now protected by FSA diverted under Park Farm Rd
27	Morehall Rec Folkestone	Aug-96	Fluvial Flooding - Large diverter chamber diverts excess flow into the Channel Tunnel Surface Relief Sewer
28	Cherry Garden Lane Folkestone	Frequent	Highway Flooding - regular occurrence (affecting some properties)
29	Folkestone	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
30	Cheriton	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
31	Enbrook Valley	2008	Fluvial Flooding - Blocked culvert resulting in property flooding

Strategic Flood Risk Assessment



ID	Location	Flooded	Notes
32	Cheriton	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
33	Cheriton	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
34	Sandgate	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
35	Sandgate Esplanade	24 October 1999 & August 1992	Coastal Flooding - Wave Overtopping during major storm events - Prior to Coast Protection Scheme (2004)
36	Horn Street (Craythorne CI)	Aug-96	Surface Water Flooding - Some properties flooded due to runoff - New FSA installed 2000
37	Seabrook	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
38	Seabrook	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
39	Lower Horn Street	1995	Groundwater Flooding - Some highway flooding (not during a fluvial event) - possibly Groundwater
40	Seabrook	Aug-96	Fluvial Flooding - 1 in 500 year flood event - Properties affected by flooding listed in Bullens Report & SDC Report # 32/093 Rep 01 Rev 1
41	Hythe - Mill Road & Stn Rd	Aug-96	Surface Water Flooding - Stn Rd Culvert blocked, properties flooded in Mill Road
42	Albert Road, Hythe	24 October 1999 & 1990	Coastal Flooding - Wave Overtopping during major storm events (approximate extents) - Prior to Coast Protection Scheme (2004)
43	West Hythe - Brockhill Stream	Before & Including 1996	Fluvial Flooding - Flooded before defence improvements in 2000
44	West Hythe - Brockhill Stream	Before & Inc 1996	Fluvial Flooding - Flooded before defence improvements in 2000
45	West Hythe - Royal Military Canal (RMC)	2001	Fluvial Flooding - Properties flooded (Approximately) RMC overtopped bank flooded garages/conservatories & some thresholds
46	West Hythe - Botolph's Bridge	2001	Fluvial Flooding - Approximate extent of flooding in 2001 - 4 properties flooded to 150mm due to canal cut overtopping

Strategic Flood Risk Assessment



ID	Location	Flooded	Notes
47	Redoubt West Hythe - Beach Estate	Jan-90	Fluvial Flooding - Canal Cut flooded (EA Notes: 07315D610FEO_JAN1990_0001 / 07315D610_JAN1990_Canal Cut_Hy)
48	Dymchurch - Marine Avenue	Either 1995 or 1997	Fluvial Flooding - From willop Sewer - approximate extents flooded in 95/97
49	Dymchurch - Wraightsfield Av	1990	Coastal Flooding - Overtopping, Damage to Seawall - prior to development in area. Unknown if properties affected
50	Dymchurch - Centre	2000	Fluvial Flooding - Tide locked river backed up and flooded near village hall (flooded properties in Orgarswick Avenue)
51	Newchurch	Pre-1979	Surface Water Flooding - EA Section 24 (5) Land Drainage Survey 1973-1979 Map #151
52	St Marys Bay - Dunstall Lane	2000/01	Fluvial Flooding - Approximate properties flooded
53	St Marys Bay	1990	Coastal Flooding - Wave Overtopping - Water on road pushed landward into some properties causing some internal flooding during large storm event
54	Littlestone - Seafront nr tower	1990s	Coastal Flooding - Wave Overtopping - No properties flooded but a large quantity of water during a large storm event
55	Littlestone	2000/01	Fluvial Flooding - Blocked channel has flooded properties in the past due to outfall becoming tide locked
56	Greatstone - Meeham Rd	2000	Surface Water Flooding - Approximate flood extents due to overwhelmed pumping station - New Romney Sewage Arm - Internal property flooding
57	New Romney - Sewage Plant	2000/01	Surface Water Flooding - Behind Queen's Rd, sewage plant backed up and flooded basin type field
58	New Romney - Herringhang Field	29/12/1999	Surface Water Flooding - Flooded Herringhang Field
59	Brenzett - Nr Church	2000 & August 2007	Fluvial Flooding - Out of bank flooding, some outbuildings and general land flooded
60	Brenzett - Moore Close	2000/01	Groundwater Flooding - Brenzett Gardens flooded
61	Snargate	Pre 1979	Surface Water Flooding - EA Section 24 (5) Land Drainage Survey 1973-1979 Map #164 - Remedial Action Taken
62	lvychurch & Brookland	Pre 1979	Surface Water Flooding - EA Section 24 (5) Land Drainage Survey 1973-1979 Map #164 - Remedial Action Taken
63	Lydd	1993	Coastal Flooding - Approximate extent of flooding due to a breach between Galloways and South Brooks - Water flowing up South Brooks sewer into S.Lydd - Inc. Army camp & some properties - Greenwall Br

Strategic Flood Risk Assessment



64	Dengemarsh Sewer	Nov-77	Coastal Flooding - Historic EA flooding records - EA Section 24 (5) Land Drainage Survey 1973-1979 Map #152
65	North Elham, Canterbury	Dec-94	Fluvial (Ordinary Watercourse) Flooding – 24 hour duration, 1 property flooded on ground floor
66	North Elham, Canterbury	Jan/Feb-01	Groundwater Flooding – 96 hours duration, 2 properties flooded ground floor up to 75mm, new raised oak floors installed. Springs and surface water run-off (Nailbourne River adjacent)
67	St Marys Drive, Etchinghill	Dec-04	Pluvial Flooding – 4 hours duration, 1 property airbrick and garage flooded, field run-off
68	St Marys Drive, Etchinghill	May-05	Pluvial Flooding – 4 hours duration, 1 property airbrick and garage flooded, field run-off
69	St Marys Drive, Etchinghill	Dec-05	Pluvial Flooding – 4 hours duration, 1 property airbrick and garage flooded, field run-off
70	St Marys Drive, Etchinghill	Feb-06	Pluvial Flooding – 4 hours duration, 1 property airbrick and garage flooded, field run-off
71	St Marys Drive, Etchinghill	Jul-07	Pluvial Flooding – 4 hours duration, 1 property airbrick and garage flooded, field run-off
72	St Marys Drive, Etchinghill	Aug-07	Pluvial Flooding – 4 hours duration, 3 properties airbrick, garage and gardens flooded, field run-off
73	10 St Marys Drive, Etchinghill	Aug-07	Pluvial Flooding - 4 hours duration, 1 property 450mm flooding to ground floor, one family displaced for 8 weeks, field run-off
74	Folkestone and Seabrook	12 th Aug-96	Multiple sources of flooding – 4 Hours duration, 400 properties internally flooded, deep flooding to basements and ground floors 2m, many families displaced for many weeks, 1 : 500 year storm, mixture of surface water, sewer and river flooding
75	Harbour area, Folkestone	11 th Jun-97	Multiple sources of flooding - 4 Hours duration, approx. 10 basements flooded. Road surface water and sewer flooding, basement flooding, flash flooding
76	Shepherds Walk, Hythe	Jan/Feb-01	Fluvial (Main River) Flooding - Royal Military Canal over topped bank. Flooded garages, conservatories, some thresholds.
77	Botolphs Bridge Road, West Hythe	Jan/Feb-01	Fluvial (Main River) Flooding - Royal Military Canal Cut overtopped banks and flooded 4 No. properties to 150mm
78	Water Farm, Elham	Jan/Feb-01	Sewer Flooding - Public foul sewer surcharged during excessive rainfall and seriously flooded one property internally
79	Water Cottage, Duck Street, Elham	Jan/Feb-01	Fluvial (Ordinary Watercourse) Flooding - The Nailbourne River overtopped banks due to obstructions in the channel and a blocked trash grille.
80	Hog Green, Elham	Jan/Feb-01	Fluvial (Ordinary Watercourse) Flooding - The Nailbourne River overtopped banks due to obstructions in the channel and a blocked trash grille. 14 properties affected

Strategic Flood Risk Assessment



81	Marine Avenue, Dymchurch	Jan/Feb-01	Pluvial, Fluvial and Sewer Flooding - Ordinary watercourses, surface water and sewers surcharged and flooded several properties, conservatories, outbuildings.
82	Lynwood, Folkestone	10 th Nov-08	Pluvial Flooding - Surface water flooding from the playing fields at the Academy. Several gardens flooded. Water flowing from back to front and out into the roadway. Danger of water entering properties.
83	Cherry Garden Lane, Folkestone	28 th July-08, 27 th May- 08, 20 th Aug-07 & 19 th Jun-07	Pluvial Flooding - Surface water flooding to gardens and out into the roadway. Highway drainage unable to cope with flows from Cherry Garden Avenue and surrounds.
84	129a Canterbury Road, Folkestone	14 th Nov-09	Pluvial Flooding - Heavy rain flowed down Canterbury Road and then over the recently installed dropped kerb 'pram crossing'/tactile paving (Highway Authority) and into the shop. Highways Inspectors told the shop owner that as the strip of land at the rear of the footway was privately owned, then he was responsible!
85	3 Raymoor Avenue, St Marys Bay	Feb-09	Pluvial Flooding - The adjacent ditch was blocked and rain fall has caused the level to rise and risk overtopping.
86	99 and 101 Stanley Road, Cheriton	Feb-09	Pluvial Flooding - Road gullies blocked causing internal flooding to 99 and 101. Road humps adding to problem. KCC informed.
87	124,126, 128,130 Lynwood, Fokestone	Feb-09	Pluvial Flooding - Surface water run-off from the Academy playing fields. Not internal but threatening to be. Water running from the rear of the properties to the front.
88	Sandtiles, Sandling Road, Saltwood	Feb-09	Pluvial Flooding - Blocked drains leading to flooding of the road.
89	28 - 30 Spring Lane, Seabrook	Feb-09	Pluvial Flooding - Surface water run-off. Entered porch. Fire service pumped out.
90	8 Mountfield Road, New Romney	Feb-09	Pluvial Flooding - Heavy rain caused standing water which rose to the top of the door steps. Cllr Lawley requested for a soakaway to be installed and a scouring of the road. KCC request sent.
91	101 Cheriton Road, Folkestone	Feb-09	Pluvial Flooding - Water from the Highway came into the garden
92	Pedlinge Court Cottage, London Road, Pedlinge	Feb-09	Pluvial & Fluvial Flooding - Water level high in ditches and the culvert under the road unable to cope. Road flooding.
93	20 The Bayle, Folkestone	Feb-09	Pluvial Flooding - Blocked road drain, Highway flooding.
94	120B Dover Road, Folkestone	Feb-09	Pluvial Flooding - Basement flat flooded internally from the highway.
95	The Fountain Pub and Victoria Terrace, Seabrook	8 th Mar-13	Fluvial Flooding - Pub basement flooded to 1 metre due to blocked culvert on Seabrook Stream. Some porches flooded in Victoria Terrace.

Strategic Flood Risk Assessment



96	Church Fields, Stanford	27 th Nov-12	Fluvial Flooding - East Stour river overflowed via a road drain into the cul de sac. Thresholds reached at 3 and 4 Church Fields.
97	4 Water Farm, Elham, Canterbury	28 th Jan-14	Pluvial Flooding - Pump Station failed. Drains surcharged - heavy rain.
98	Gate House, North Elham Hill, Canterbury	Feb-14	Groundwater Flooding - High water table filled the underfloor voids and broke through into ground floor. Depth is underfloor.
99	Robin Hood, North Elham Hill, Canterbury	Feb-14	Groundwater Flooding - High water table filled the underfloor voids and broke through into ground floor. Depth is underfloor.
100	Pear Tree Cottage, North Elham Hill, Canterbury	Feb-14	Groundwater Flooding - High water table filled the underfloor voids and broke through into ground floor. Depth is underfloor.
101	Waterside, Ashford Road, New Romney, Kent	Dec-13	Pluvial Flooding - Flooded garden to 600mm deep with water soaking through walls causing internal dampness.